

NATIONAL SAFETY ALERT

Crane Safety Alert

Yong Mao STT 293 Tower Cranes

This health and Safety alert is a result of an inspection by the crane operator of the slew ring after hearing a clunk whilst lifting and slewing a shutter.

On inspection the crane operator found that one of the slew ring teeth had been dislodged.

A crack test was conducted on the remaining slew ring teeth which found that each tooth of the slew ring failed that crack test.

ACTION REQUIRED

Immediately have all Yong Mao STT 293 tower Cranes removed from service until the slew ring is independently inspected and crack tested by a suitably qualified engineer.

Evidence of the completed inspection results must be forwarded to the CFMEU Health and Safety Co-ordinators before the tower crane can be returned to service.

CFMEU ACT Branch:

02 6267 1599

CFMEU QLD/NT Branch:

07 3231 4600

CFMEU NSW Branch:

02 9749 0400

CFMEU SA Branch:

08 8231 5532

CFMEU WA Branch:

08 9221 1055

CFMEU VIC/TAS Branch:

03 9341 3444



Safety is union business.
STAND UP. SPEAK OUT. COME HOME.